

MISSOURI DEPARTMENT OF HEALTH STATE-PUBLIC HEALTH LABORATORY

RECEIVED By Breath Alcohol at 1:42 pm, May 06, 201 DATAMASTER MAINTENANCE REPORT Complete this report in duplicate at the time of the regular monthly preventive maintenance check, and whenever instrument is repaired. Send copy to Department of Health; retain original in department file. DATAMASTER SN DATE OF INSPECTION 04-23-2010 LOCATION OF INSTRUMENT (STREET AND CITY) TIME QEINSPECTION US 160 GREENE COUNTY BAT VAN CHECKLIST: Place a check (✓) to the left of each item if found to be satisfactory or if operating within established limits. (Write in observed values where determined.) Unchecked items must be corrected before using instrument. DIAGNOSTIC CHECK (PRINTOUT ATTACHED) COMPUTER DETECTOR PROGRAM T FILTERS HEATERS SAMPLE CHAMBER 🗹 QUARTZ STANDARD FLOW DETECTOR **M** CALIBRATION PRINTER ☑ PUMP HIGH SPEED 1 INDICATOR LIGHTS TIME AND DATE \blacksquare SIMULATOR TEMPERATURE (34 °C ± 0.2°C) LE CALIBRATION CHECK -Run three tests using a standard solution. All three tests must be within \pm 5% of the standard value and must have a spread of .005 or less. Check the box corresponding to the standard solution being used. (PRINTOUT ATTACHED) (USE RECIRCULATION PUMP) 🗹 0.100% STANDARD - MUST READ BETWEEN 0.095% and 0.105% INCLUSIVE ☐ 0.040% STANDARD - MUST READ BETWEEN 0.038% and 0.042% INCLUSIVE (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT) PERFORM R.F.I. TEST (PRINTOUT ATTACHED) M NUMBER OF REFUSALS, SINCE LAST MAINTENANCE REPORT, AND NUMBER OF BREATH TESTS IN EACH RANGE AS (DO NOT INCLUDE SIMULATOR TESTS) REFUSALS ((.05-.09)(0-.04)(.10-.14)(.15-.19)List any new parts and describe any alteration or modification that was made to restore the instrument to operate satisfactorily and within established limits (use other side if necessary) INGUNENT MITHEN KEPLO MARKETENG SOLUTION

INSPECTING OFFICER	
SIGNATURE	PRINT NAME
7/1/2-1	M.L. CARY
TYPE II PERMIT NUMBER/EXPIRATION DATE	TELEPHONE NUMBER
1767.48 12,07.11	1 417,855.6868

CERTIFICATE OF ANALYSIS

MANUFACTURER AND SUPPLIER: RepCo Marketing, Inc. LOT NUMBER: 09002
EXPIRATION DATE: August 31, 2011 at 11:59 p.m.

RepCo Marketing, Inc. certifies the following:

RepCo Marketing, Inc. manufactured, tested and supplied Lot Number <u>09002</u> of Alcohol Certified Solution for simulators. Random samples of said lot number were analyzed by an independent laboratory utilizing a gas chromatograph and found to contain <u>.1206</u> gms/dl +/-.003 gms/dl wt/vol ethanol (95% Confidence).

The alcohol and distilled water used in the solution were found to be free of any interfering substance.

This solution will produce a vapor alcohol value of <u>.100</u> +/-3% gms/210L Breath when heated to 34 Degrees Celsius +/-0.2 Degrees Celsius in a simulator (95% Confidence).

The date of manufacture for this lot number is September 1, 2009.

The expiration date for this lot number is August 31, 2011 at 11:59 p.m.

This document is a true representation of the original Certificate of Analysis.

Cecil B. Garner, President RepCo Marking, Inc.

State of Missouri DEPARTMENT OF HEALTH



MO 580-0771 (7-88)

PERMIT TYPE II



Lab. 4 (A7-88)

MICHAEL L CARY

DATAMASTER

is	hereby	authorized	to	instruct	and	supervise	operators,	train	instructors,	inspect,
ca	librate, p	perform field	l re	pairs, and	i ope	rate the fol	lowing brea	ith ana	alyzer(s):	

for the determination of the alcoholic content of blood from a sample of expired (alveolar) air. Issued under the provisions of sections 577.020 through 577.041, RSMo 1986. Date 12/2/09 Interim Director Director of State Public Health Laboratory Margart 1. Denuelly Director, Department of Health

Face This Side Down - This Edge In First

BAC DataMaster Evidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 204086 04/23/10

TESTING OFFICER:
CARY/M/L,
OFFICER I.D.: 0553
PERMIT NUMBER: 920248
EXPIRATION DATE: 12/02/11
MISCELLANEOUS DATA:

--- SUPERVISOR MODE ---

BLANK TEST	. 666	21:56
INTERNAL STANDARD	WERIFIED	21:56
EXTERNAL STANDARD	. 102	21:56
BLANK TEST	. 000	21:57
EXTERMAL STANDARD	. 103	21:57
BLANK TEST	. 888	21:59
EXTERMAL STANDARD	. 103	21:58
BLANK TEST	.000	21:59

N = 3 |SIM. = .1 |AVG. = .1026 Face This Side Down - This Edge In First

BAC DataMaster Evidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 204086 04/23/10 21:53

--- DIAGNOSTIC CHECK ---

COMPUTER: OKAY FROGRAM (04-07-2009): OKAY HEATERS SAMPLE CHAMBER: 49c FLOW DETECTOR: OKAY PUMP HIGH SPEED: OKAY DETECTOR: OKAY FILTERS: OKAY QUARTZ STANDARD: OKAY CALIBRATION: OKAY

PRINTER TEST

 $!"\#s\%&'()*+,-.../0123456789::(=)?@ABCDEFG\\ HIJKLMNOFQRSTUVWXYZ[\]^_'abcdefqhi.jklmnooqrstuvwxuz(<math>!$) \rightarrow

Operator Signature WALL

Operator Signature_

2208-05

Face This Side Down - This Edge In First

BAC DataMaster Evidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 204086 04/23/10

ARREST TIME: 21:00 SUBJECT NAME: RFI/TEST DOB: 01/01/01 SEX: M STATE/D.L.: MO/12345 ARRESTIMG OFFICER: CARY OFFICER I.D.: 553 TESTING OFFICER: CARY OFFICER I.B.: 553 PERMIT NUMBER: 920248 EXPIRATION DATE: 12/02/11 MISCELLAMEOUS DATA:

--- BREATH AMALYSIS ---

BLANK TEST INTERMAL STANDARD

.000 VERIFIED 21:52

21:52

RADIO INTERFERENCE

MILL